

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 02/19/2013	3. Time Prepared 1600
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 2/11/2013 – 0700, 2/25/2013
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, TX
8. Activity Log			
Time	Major Events		
0900	<ul style="list-style-type: none"> <li>Attended the EPA C&amp;G meeting.</li> </ul>		
09:45	<ul style="list-style-type: none"> <li>Arrived at C0.4 boat launch and joined my Enbridge counterpart.</li> <li>C0.4 Boat launch river conditions observed.</li> <li>MP5.75 Ceresco Dam impoundment river conditions observed.</li> <li>MP5.63 Ceresco Dam impoundment river conditions observed.</li> <li>Ceresco Dam impoundment river conditions observed.</li> <li>C3.2 Pole Barn observed core logging.</li> <li>C3.2 Observed river conditions.</li> <li>MP15.25 South Mill Pond river icing conditions observed.</li> <li>MP15.75 North Mill Pond river icing conditions observed.</li> <li>MP21.5 River conditions observed.</li> <li>MP26.25 RDB observed the RI crew.</li> <li>MP26.0 Sediment trap river conditions.</li> <li>MP27.0 Shady Bend Campground river conditions observed.</li> <li>E2 Boat launch observed river conditions.</li> <li>Morrow Lake water conditions.</li> <li>Morrow Lake Delta Neck river conditions observed.</li> <li>Morrow Lake Delta river conditions observed.</li> <li>MP10.5 Sediment trap icing conditions observed.</li> <li>MP10.4 Sediment trap icing conditions observed.</li> </ul>		
1400	Returned to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			